FIG. 1A

#3





FIG. 1B






FIG. 2




FIG. 3





FIG. 4






FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16





FIG. 18







FIG. 19

FIG. 20A -0.75 50 8 CYL -0 -0 -0 SPH -0.00 -0.25 IV -0.50 -0.75 -1.00 -1.25 -1.50 -1.75 -2.00 111 -2.25 -2.50 -2.75 -3.00 -3.25 -3.50 -3.75 -4.00 -4.25 -4.50 -4.75 -5.00 -5.25 -5. 50 -5.75 -6.00 -6.25 -6.50 -6.75 -7.00 -7.25 -7.50 -7.75 -8.00



+1.75






FIG. 21








FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26

FIG. 27A

00	7.5	1.50	25	00	7.5	20	25	00	CYL/
-2.00	-1.75	<del>-</del>	-1.25	-1.00	-0.75	-0.50	-0.25	<u>-</u> 0	SPH
									-0.00
				<del></del>					-0.25
				. V	. — !				-0.50
									-0.75
									-1.00
									-1.25
									-1.50
									-1.75
				IV					-2.00
								-2.25	
									-2.50
-	_								-2.75
		_							-3.00
		_							-3.25
'						_			-3.50
									-3.75
				Ш					-4.00
									-4.25 -4.50
						_			-4. 75
									-5.00
		- 1							-5. 25
			-			+	_		-5.50
	+							-	-5.75
	$\dashv$				_		1		-6.00
			<del>-</del>	II ,	+	<del></del>	_		-6.25
	7	-			<u>i</u>				-6.50
	<del>-</del>	寸		1	Ì				-6.75
									-7.00
		ĺ							-7.25
				1					-7.50
				<u> l</u>					-7.75
									-8.00

FIG. 27B




FIG. 27C

CYL SPH	-0.50	-0.75	-1.00	-1.25	-1.50	-1.75	-2.00
+0.25							
+0.50					V		
+0.75					•		
+1.00		•					
+1.25						\/	ı
+1.50						_ ,	,
+1.75							

